



Operations Report: Otter Rock July 2026

Base Operations

1. 07/23 - Meter read system

Spring flow – June 26

Source	Flow rate GPM
Spring 1 flow rate	30
Spring 2 flow rate	38
Spring 3 flow rate	32
Reservoir overflow rate	47

Spring flow – July 26

Source	Flow rate GPM
Spring 1 flow rate	26
Spring 2 flow rate	24
Spring 3 flow rate	31
Reservoir overflow rate	30




Distribution Overview (July 2026)

Master Meter Usage: 663,000 gallons

Distribution Loss: 35,155 gallons

Loss Factor: 5.30%

Gallons per minute loss: 0.79 GPM






Compliance Analysis

Samples Collected:

07/15 – Monthly Routine Coliform

Chlorine levels

	First User	Distribution System
Average	0.23 ppm	0.24 ppm
High	0.25 ppm	0.27 ppm
Low	0.21 ppm	0.20 ppm





Additional Services

1. 07/02 – Locate at 825 1st st.
2. 07/30 – Locate at 6835 Ellie Ave per Rod.

Recommended Maintenance

1. Install air relief valves in the distribution system to prevent the air lock from occurring again. Ensure they are planned for and included in the system's rebuilding.

Administrative Comments