



Operations Report: Otter Rock March 2026

Base Operations

1. 03/22 - Meter read system

Spring flow – Feb 26

Source	Flow rate gpm
Spring 1 flow rate	60
Spring 2 flow rate	129
Spring 3 flow rate	36
Reservoir overflow rate	129

Spring flow – March 26

Source	Flow rate gpm
Spring 1 flow rate	180
Spring 2 flow rate	900
Spring 3 flow rate	36
Reservoir overflow rate	129




Distribution Overview (March 2026)

Master Meter Usage: 365,000 gallons

Distribution Usage: 392,234 gallons

Distribution Loss: -27,234 gallons

Loss Factor: -7.5%






Compliance Analysis

Samples Collected:

03/25 – Monthly Routine Coliform

Chlorine levels

	First User	Distribution System
Average	0.275 ppm	0.251 ppm
High	0.33 ppm	0.34 ppm
Low	0.22 ppm	0.20 ppm





Additional Services

1. 03/03 – Locate at 6610 Otter Crest Loop
2. 03/09 – Monthly reporting
3. 03/10 – Board meeting
4. 03/13 – Replace register heads at 845 1st and 145 Mahala.

Recommended Maintenance

1. Install air relief valves in the distribution system to prevent the air lock from occurring again. Ensure they are planned for and included in the system's rebuilding.

Administrative Comments

NA