



Operations Report: Otter Rock Water District

August 2026

Base Operations

1. 09/23/26 - Meter reading was completed for the system (sent to ORWD on 9/24)

Spring flow – August 21, 2026

Source	Flow rate GPM
Spring 1 flow rate	21
Spring 2 flow rate	16
Spring 3 flow rate	30
Reservoir overflow rate	50

Spring flow – September 23, 2026

Source	Flow rate GPM
Spring 1 flow rate	19
Spring 2 flow rate	08
Spring 3 flow rate	31
Reservoir overflow rate	54




Distribution Overview (September 2026)

Master Meter Usage: 647,000 gallons

Distribution Loss: 49,480 gallons

Loss Factor: 7.6%

Gallons per minute loss: 1.15 GPM





Compliance Analysis


Samples Collected:

09/22/26 – Monthly Routine Coliform

09/29/26 - Annual Source Assessments

Chlorine levels

	First User	Distribution System
Average	0.32 ppm	0.32 ppm
High	0.44 ppm	0.41 ppm
Low	0.23 ppm	0.24 ppm





NW Natural
WATER™

Additional Services

Locate was performed on 6610 Otter Crest Loop.
Leak checks were performed at 325 3rd St. and 6240 C Ave.

Recommended Maintenance

Install air relief valves in the distribution system to prevent the air lock from occurring again. Ensure they are planned for and included in the system's rebuilding.

Administrative Comments

Crews will be dispatched to repair the leaking angle stop at 333 4th St. in the first week of October.