



Phone: 503-554-8333
1-855-554-8333 (TF)
Mail: P.O. Box 699
Newberg, OR 97132
Email: info@hilandwater.com
Internet: www.hilandwater.com

February 13, 2023

Otter Rock Water District Monthly Operations Report: January 2023

Spring flow – January 2, 2023

| Source | Flow rate |
|-------------------------|-----------|
| Spring 1 flow rate | 69 gpm |
| Spring 2 flow rate | 300 gpm |
| Spring 3 flow rate | 36 gpm |
| | |
| Reservoir overflow rate | 113 gpm |

February preview: Spring flow – February 1, 2023

| Source | Flow rate |
|-------------------------|-----------|
| Spring 1 flow rate | 82 gpm |
| Spring 2 flow rate | 300 gpm |
| Spring 3 flow rate | 33 gpm |
| | |
| Reservoir overflow rate | 113 gpm |

Chlorine levels

| | First User | Distribution System |
|---------|------------|---------------------|
| Average | 0.21 ppm | 0.25 ppm |
| High | 0.33 ppm | 0.32 ppm |
| Low | 0.15 ppm | 0.15 ppm |

Other notable activities during the month:

During routines, Cody cleaned sheds of chlorine old chlorine jugs and boxes.

The annual usage report for Oregon Water Resources Department was submitted.

JJ Olson continued correspondence with Lincoln County to determine DBP sampling locations. He sent a map to Amy Bleekman at OHA and Kaline Chavarria at Lincoln County.

On January 4, Cody responded to an emergency locate request submitted by Central Lincoln PUD to replace a primary pole near 1st and Gladys.

On January 17, Cody responded to an emergency locate request submitted by PLI Systems to repair an eroded slope.